

# Errata to IEEE Recommended Practice for Motor Protection in Industrial and Commercial Power Systems


Developed by the  
**Technical Books Committee**  
of the  
**IEEE Industry Applications Society**

*Correction Sheet*  
**8 December 2021**

Copyright 2021 by the Institute of Electrical and Electronics Engineers, Inc. All rights reserved.  
Published 8 December 2021. Printed in the United States of America.

This correction sheet may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. This correction sheet may not be sold, licensed, or otherwise distributed for any commercial purposes whatsoever. The content of this correction sheet may not be modified.

*In subclause 6.10, switch the positions of Figure 11a) and Figure 11b) to display as follows:*



a) Thermal overload curves, cold

b) Thermal overload curves, warm

Courtesy of Schneider Electric

**Figure 11—Thermal overload curves, a) cold and b) warm**